PHYTOVISTA LABORATORIES

Stubbs Lane, Beckington, Frome, BA11 6TE, UK
Tel: +441373470418
email: info@phytovistalabs.com
Web: www.phytovistalabs.com

CERTIFICATE OF ANALYSIS

No. C-AR0673-5-1

Sample Information		
Description: Oil Sample 5	Sample condition: Good	Test performed date: 16/09/2019
PV ID: AR0673-5	Received date: 09/09/19	Test method: PVSOP-01
Batch no: N/A	Test location: On Site	
Customer Information		
Name: CBD Life UK	Address: Unit 9E Victoria IND. EST. Hebburn, Tyne and Wear, NE311UB	
Method Information		

Results apply to sample as received

CANNABINOID PROFILE

Analyte	%w/w
CBDV	0.08
CBDVA	ND
CBG	0.19
CBD	8.38
THCV	ND
CBDA	2.17
CBGA	0.02
CBN	0.02
Δ9-THC	0.16
Δ8-THC	ND
THCVA	ND
CBC	0.14
THCA	0.05
CBCA	0.07



CBC = Cannabichromene
CBD = Cannabidiol
CBDA = Cannabidiolic acid
CBDV= Cannabidivarin
CBDVA = Cannabidivarinic acid
CBG = Cannabigerol
CBGA = Cannabigerolic acid
CBN = Cannabinol
CBCA = Cannabachromenic acid
Δ9-THC = Δ9-tetrahydrocannabinol
Δ9-THCA = Δ9-tetrahydrocannabinolic acid
THCV = Tetrahyrdocannabivarin
THCVA = Tetrahydrocannabivarinic acid
Δ8-THC = Δ8-tetrahydrocannabinol

Additional Information:

ND= Not Detected

Digitally Controlled Document
CHECKED AND AUTHORISED

Digitally signed by Katarina Rigdova
Date: 2019.09.16 16:59:02 +01'00'

Use the QR code to check your results and find out more information on how to read them.

The test results relate only to the samples tested. By placing the order for services with PhytoVista Laboratories, terms and conditions are deemed to be accepted by the submitter. Report shall not be reproduced, except in full, without the approval of the testing laboratory.